

## Work Order (Bid Form)

Knoxville/Knox County Community Action Committee



## **WORK ORDER INFORMATION**

Work Order Name: WO/80008KN0271/1

Work Order Type: Weatherization

Audit Name: 80008KN0271-Audit

**CLIENT INFORMATION** 

Client Name:

Address:

Client ID: 80008KN0271

Alt. Client ID: KNOX

**AGENCY INFORMATION** 

Agency: Knoxville/Knox County CAC

Address: P.O.Box 51650

Knoxville, TN 37950-1650

Agency Phone: (865) 244-3080

Fax: (865) 544-1647

Email Address: jason.estes@cachousing.org

Company Name & License Number:	 		
Contractor's Signature:			

## <u>COMMENT</u>

Single Family Dwelling

Contractor to follow 2006 International Residential Code as adopted by the City of Knoxville or Knox County as applicable.

City

House built in 1960

An EPA Certified Firm/Renovator is required.

Client Name:

Client ID: 80008KN0271 Alt. Client ID: KNOX Work Order (Bid Form)

Work Order Name: WO/80008KN0271/1

Report Run On: 5/8/2010

DOE Weatherization Assistant

Version 8.6.0 Page 1 of 8

N	leasure 1	Double Pane Replacement (Feet) (N1)	(10 Squar	e	Componen	ts			Inspected	
Co	<i>mment</i> Re Fie	fer to Appendix A- Standards t ld Guide.	for Weath	erizati	on Materials	and Sou	ıtheast			
				_	Estimated			Actual		
#	Material / Lab	or Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1	Windows	Double Pane Replacement (10 Square Feet)	Each	1				***************************************		
		Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide.								
2	Labor	Labor	Each	1						
Ot	her Detail									
						73000				
				Measur	e Sub Total:	***************************************	] ;	Sub Total:		
F	Field Notes:									

Measure 2 DW	/H Pipe Insulation			Componen	ts			Inspected
Comment				·				
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	DHW Pipe Insulation	Each	1					:
	Includes labor cost. All corners must be cut properly. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide.						1	
2 Labor	DHW Pipe Insulation	Each	1					
Other Detail								
					********			
			Measur	e Sub Total:	*****	1	Sub Total:	
Field Notes:							L	

	Measure 3 DWH	Tank Insulation			Componen	ts			Inspected
C	<b>comment</b> extend p	ressure relief pipe as ne	eded						
					Estimated	•		Actual	-
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Hot Water Equipm	DHW Tank Insulation	Each	1					
		Includes labor cost. R-10 minimum. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide.							
2	Labor	DHW Tank Insulation	Each	1					
C	Other Detail								
						* *			
	-								
				Measur	e Sub Total:	11 11000	] ;	Sub Total:	
	Field Notes:		******		- · · · · · · · · · · · · · · · · · · ·				
									- Allendaria

Report Run On: 5/8/2010

1	Measure 4	-loor ins. R-19			Componen	ts F1			Inspected
C	omment								
	befo Stan subf (e.g. com	udes labor cost. Contractor's re installing insulation. Contr dards. Insulation is installed loor above (paper side agair staves for blankets). Insula pressions. Refer to Append Southeast Field Guide.	ractor to in d to maintanst nst subfloo nation to hav	istall u ain per r) inclu ve NO	sing Resnet manent cont uding necess gaps, voids,	Grade 1 act with t ary supp or	he orts		
					Estimated	! 	T	Actual	
ŧ	Material / Labor	r Description / Comment	Units	Qty	Unit Cost	Total	Qty	<b>Unit Cost</b>	Total
1	Insulation	Floor Insulation - Fiberglass Batts - R-19	SqFt	756	***************************************				
2	Labor	Floor Insulation - Fiberglass Batts - R-19	SqFt	756					
C	ther Detail								
		•		Measur	e Sub Total:			Sub Total:	
	Fleid Notes:				, , , , , , , , , , , , , , , , , , , ,				

1	Measure 5 CO l	Monitor is Needed	••••		Componen	ts			Inspected
C	<b>comment</b> Refer to Field Gu	Attachment A- Standard iide.	s for Wea	theriza	ation Materia	ls and So	outheas	st	
					Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety	CO monitor	Each	1					
		Refer to Attachment A- Standards for Weatherization Materials and Southeast Field Guide.					<u> </u>	]	
2	Labor	Labor	Each	1					
C	ther Detail								
	ma .								
			i	Measur	e Sub Total:			Sub Total: [	
	Fleld Notes:	11000				77.70.4			THE COLUMN TO TH

Measure 6 Fix I	mproper Venting (Clothe	s Dryer	)	Component	s		1	nspected
protrudir is 15 fee	ents installed with damper ng through pipe. Must be v et. No changes allowed. R rization Materials and Sou	ented to tefer to A	outsic \ttachn	le of home. Nent A- Stand	/laximum	length	ı	
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Health and Safety	Dryer Vent w/ Metal Piping (upto 15' in length)	Each	1					
	Refer to Attachment A- Standards for Weatherization Materials and Southeast Field Guide.							
2 Labor	Labor	Each	1					
Other Detail								
			Measur	Sub Total:			Sub Total:	
Fleld Notes:	***************************************			·			***************************************	

Client ID: 80008KN0271 Alt. Client ID: KNOX Work Order Name: WO/80008KN0271/1 Report Run On: 5/8/2010

Page 7 of 8

,	<i>Measure</i> 7 Vap	or Barrier Needed (QTY	756 SF)		Componen	ts			Inspected
C	walls an earth. M	6 mil poly. Must be insta d support piers. Must be lust be secured at all sea rization Materials and So	securely ms. Refer	fastene to Atta	ed. Must be achment A- :	cleated	down to	1	
					Estimated			Actual	
ŧ	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
į	Health and Safety	Basement /Crawlspace Vapor Barrier	SqFt	756					
!	Labor	Labor	SqFt	756					
C	ther Detail								
_									
			1	Measure	Sub Total:		] 8	Sub Total:	
	Field Notes:					***************************************			
			Work Ord	der Grai	nd Total:		Grand	l Total:	

Client ID: 80008KN0271 Alt. Client ID: KNOX Work Order Name: WO/80008KN0271/1 Report Run On: 5/8/2010

Page 8 of 8